




275 Grandview Avenue
Suite 300
Camp Hill, PA 17011
717-763-7331

August 1, 2006

Mr. David Bonenberger, B.S.
Saucon Valley School District
2097 Polk Valley Road
Hellertown, PA 18055



RE: Loss Control Contact
Policy CBP 9796390
Report ID 2006-b24rwz

Dear Mr. Bonenberger,

This letter confirms my visit on July 31, 2006 for purposes of reviewing the high school swimming pool as to the 1-meter diving board issue.

As a result of this visit there is one recommendation being submitted and is listed on the next page. A similar recommendation was submitted about 3-years ago during my initial survey inspection of the school buildings.

Please review this item and respond in writing in the enclosed envelope within 30-days with a decision on this matter and any corrective action needed.

I thank you for the courtesies extended to me during the visit and please do not hesitate to call with any questions.

Sincerely,

Emil F DiTullio, CFPS, ARM
Loss Prevention Technical Consultant

cc: 3238458 Weiss-Schantz Agency Inc

This confirmation of service concerns only such conditions and practices as were observed and considered during the visit. It does not purport to list all hazards. Neither does it purport to indicate that other hazards do not exist, either now or at the time of the visit, nor that you are in compliance with federal, state, or local safety and health laws and codes. No loss control advice, observation, recommendation, or other service shall be construed as having any bearing as to the applicability of your policy in the event of a loss. In all instances, the policy alone determines the coverage provided.

Peerless Insurance Company (Not Licensed in New Jersey)
Peerless Indemnity Insurance Company

Excelsior Insurance Company
The Netherlands Insurance Company

Recommendations

2006-07-01 : SWIMMING POOL DIVING:

The current pool depth beneath the area that once contained the 1-meter diving board is 10 1/2-ft., and I was told the water level is actually maintained less than the marked depth.

Current state requirements outline a 12-ft. water depth to be maintained beneath a 1-meter diving board or platform.

Based on this current requirement it is recommended the diving board should not be reinstalled unless the depth is changed to 12-ft.